



### Surface SWYPE for Acid/Base Cat. No. 769-1026

1. Lightly spray the area or item (e.g., workbench, tool, control knob) with Developing Solution for Acid/Base Cat. No. 769-1066.
2. Wait at least 30 seconds and then wipe with a Surface SWYPE pad.
3. The acid detector will change from neutral (orange) color to fuchsia/magenta at pH 3. For caustic exposures, the indicator will change to blue at pH 9.5.

#### **SKC Limited Warranty and Return Policy**

SKC products are subject to the SKC Limited Warranty and Return Policy, which provides SKC's sole liability and the buyer's exclusive remedy. To view the complete SKC Limited Warranty and Return Policy, go to [skcinc.com/warranty](http://skcinc.com/warranty).